
Textiles F.R. Limited





Unit 4B, (30) Wharfedale Road **Euroway Trading Estate** Bradford West Yorkshire BD4 6SG

Tel: 01274 651230 Fax: 01274 651305 E-mail: sales@textilesfr.co.uk

Web site: www.textilesfr.co.uk

Test Report & Certificate

UKAS TESTING LABORATORY No.1413

British Standard Flammability Test Document: 21360 Page 1 of 1

Test Method : BS EN ISO 15025:2002

Specification: BS5867-2:2008:Type B

Contract Curtain Test

Customer Account: SAH003 SAHCO GMBH KREUZBURGER ST 17-19

D-90471 NURNBERG GERMANY

Order Details TFR Order No

: 251862

Fabric Composition : 1.0

Quantity (metres) : 5K
: 12/03/2019
: 600187 BALBOA
: 1.0

Sample Conditioning

: Test specimens were conditioned in an atmosphere having a temperature of 20°C +/--2°C and Relative Humidity 65% +/- 5 % for a minimum of 24 hours prior to testing.

Test Enclosure Conditions

Relative Humidity 68 % : Temperature 20 'C

Cleansing Procedure

Flammability testing was performed without the durability requirements stated in Section 5 of BS5867-2:2008 being completed.

Other Details Sample Treatment

Sample tested in an as received state

Test Procedure: Six specimens were prepared each measuring 200mm +/- 2mm x 160mm +/- 2mm, three with the longer dimension in the length and three with the longer dimension in the width λ butane flame was applied to the sample face for 15 seconds.

Report Notes: This test was carried out in accordance with BSEN ISO 15025 Procedure A. The results may not apply to situations where there is a restricted air supply or prolonged exposure to large sources of heat such as in a conflagration.

OBSERVATIONS	Warp Rep1	Direc Rep2		Weft Repl	Direc Rep2	_
Flame reached an edge	No	No	No	No	No	No
Hole reached an edge	No	No	No	No	No	No
Flaming debris	No	No	No	No	No	No

Comments:

COMPLIANCE REQUIREMENTS: No part of any hole nor any part of the lowest boundary of any flame shall reach the upper edge or either vertical edge of any specimen and there shall be no separation of flaming debris from any specimen.

The sample complied with the requirements for BS5867-2:2008:Type B Flammability testing was performed without the durability requirements stated in Section 5 of BS5867-2;2008 being completed.

Conducted by : Mr.R. BERRY

Mr.R. BERRY / Hum Laboratory Technician

Authorised by: Miss K. BUTTOM

Date 18/03/2019

Date 18/03/2019