

DANISH TECHNOLOGICAL

Gregersensvej

DK-2630 Taastrup Tel. +45 72 20 20 00 Fax +45 72 20 20 19

info@teknologisk.dk www.teknologisk.dk

Page 1 of 2

Initials Chf/leln

Order no.: 131724

No. of appendix: 1

Test Report

Report No.: 131724-1

Assignor: Kvadrat A/S

Lundbergsvej 10 8400 Ebeltoft

Subject: Cutting of curtain fabric, designated: Air 4, 0100

Fiber composition: 100% Trevira CS (as per info from the assigner).

Approx. mass per unit area: 71 g/m².

Sampling: The test material was sampled by the client and received at the Danish Technological

Institute 01.04.2022

Method: Testing of flammability according to Federal Aviation Regulations, FAR § 25.853(a),

appendix F, part I (a) (1) (ii). Vertical test: Bunsen burner flame is applied to specimen

for 12 sec. (ignition time).

Details of the test are given on page 2.

Period: The testing was completed 06.04.2022

Result:

Test (ii) 12 sec.	Average After flame Time [sec.]	Average Drip Extinguishing Time [sec.]	Average burn length
Warp			
	0	0	180 mm (7.08 inch)
Weft			
	0	0	177 mm (6.95 inch)
Requirements for			
passing:	<15	<5	203 mm (8 inch)

According to the requirements of flammability specified in FAR § 25.853(a), appendix F, part I (a) (1) (ii) the upholstered fabric **meets** the requirements for passing.

Storage: The test material will be destroyed after 3 months, unless otherwise agreed.

Terms: This test was conducted accredited in accordance with international requirements (ISO/IEC

17025:2017) and in accordance with the General Terms and Conditions of Danish Technological Institute. The test results solely apply to the tested item. This test report may be quoted in extract

only if Danish Technological Institute has granted its written consent.

Date/place: 07.04.2022, Danish Technological Institute, Textile, Taastrup

Signature: Test responsible Co-signatory







Report no.: 131724-1 Page: 2 of 2 Initials: Chf/leln

Results continued:

The test results relate only to the ignitability of the combination of materials under the particular conditions of test; they are not intended as a means of assessing the full potential fire hazard of the materials in use.

Test method: FAR § 25.853(a), appendix F, part I (a) (1) (ii)

Ignition source: Bunsen burner flame

Conditioning atmosphere: 23 ± 2 °C / 50 ± 5 % RH.

Three specimens in each fabric directions were tested. The flame was applied for 12 sec. as specified for materials covered by paragraph (a) (1) (ii) of part 1 of appendix F.

Test (ii) 12 sec.	After flame Time [sec.]	Drip Extinguishing Time [sec.]	Burn length
	0	0	177 mm (6.97 inch)
Warp	0	0	180 mm (7.09inch)
	0	0	182 mm (7.17inch)
Average	0	0	180 mm (7.08 inch)
-	0	0	185 mm (7.28 inch)
Weft	0	0	190 mm (7.48 inch)
	0	0	150 mm (6.10inch)
Average	0	0	177 mm (6.95 inch)
Requirements for passing, average:	< 15	< 5	203 mm (8 inch)

Comments: The

The upholstered fabric specimens **meet** the requirements for passing.

DANISH TECHNOLOGICAL INSTITUTE

Report no.: 131724-1

Appendix: 1
Page: 1 of 1
Initials: Chf/leln

