## **Test Report**

Report No.: A 867940-1



Gregersensvej DK-2630 Taastrup Tel. +45 72 20 20 00 Fax +45 72 20 20 19

info@teknologisk.dk www.teknologisk.dk

Page 1 of 1

Order no.: 867940

No. of appendices: 1

Chf/leln

**Assignor:** Kvadrat A/S

Lundbergsvej 10 8400 Ebeltoft

Attn.: Lone Henriksen

Subject: Upholstery fabric Jaali, 92% new wool, 8% nylon worsted. (as per info from the as-

signer).

Sampling: The test material was sampled by the client and received at the Danish Technological In-

stitute 11.04.2019

**Method:** See Appendix 1.

**Period:** The testing was completed 13.05.2019

**Result:** Individual results appear from Appendix 1.

**Storage:** The test material will be destroyed after 6 months, unless otherwise agreed.

Terms: The accredited test was carried out according to DANAK's general conditions see <a href="https://www.danak.dk">www.danak.dk</a> and according to

the General Terms and Conditions regarding Commissioned Work Accepted by the Danish Technological Institute, which apply at the time of signing the agreement. The test is only valid for the tested specimen. The test report

may only be extracted, if the laboratory has approved the extract.

Date/place: 14.05.2019, Danish Technological Institute, Wood and Biomaterials, Textile, Taastrup

**Signature:** Test responsible Co-signatory







A 867940-1

Report no.: Appendix: Page: 1 of 3 Initials: Chf/leIn

Test Methods	Results	
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	101 Colour fastness:	6
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	121 Colour fastness:	6-7
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	141 Colour fastness:	6
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	171 Colour fastness:	6
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	201 Colour fastness:	6
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	341 Colour fastness:	7
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	351 Colour fastness:	7
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	561 Colour fastness:	6



A 867940-1

Report no.: Appendix: Page: 2 of 3 Initials: Chf/leIn

Test Methods	Results	
Colour fastness to artificial light	791	
DS/EN ISO 105:B02:2014	Colour fastness:	6
Method 2		
1-8 scale, 8 best rating		
Normal conditions		
Apparatus: Atlas Ci4000 Xenon		
Weather-Ometer		
Colour fastness to artificial light	871	
DS/EN ISO 105:B02:2014	Colour fastness:	6
Method 2		
1-8 scale, 8 best rating		
Normal conditions Apparatus: Atlas Ci4000 Xenon		
Weather-Ometer		
Colour fastness to artificial light	951	
DS/EN ISO 105:B02:2014	Colour fastness:	7
Method 2	Coloui lastiless.	/
1-8 scale, 8 best rating		
Normal conditions		
Apparatus: Atlas Ci4000 Xenon		
Weather-Ometer		
Colour fastness to artificial light	961	
DS/EN ISO 105:B02:2014	Colour fastness:	6
Method 2		
1-8 scale, 8 best rating		
Normal conditions		
Apparatus: Atlas Ci4000 Xenon Weather-Ometer		
Colour fastness to artificial light	F74	
DS/EN ISO 105:B02:2014	571 Colour fastness:	7
Method 2	Colour fastiless.	/
1-8 scale, 8 best rating		
Normal conditions		
Apparatus: Atlas Ci4000 Xenon		
Weather-Ometer		
Colour fastness to artificial light	591	
DS/EN ISO 105:B02:2014	Colour fastness:	6
Method 2		
1-8 scale, 8 best rating		
Normal conditions		
Apparatus: Atlas Ci4000 Xenon Weather-Ometer		
Colour fastness to artificial light	611	
DS/EN ISO 105:B02:2014	Colour fastness:	6
Method 2	Colour lustricss.	J
1-8 scale, 8 best rating		
Normal conditions		
Apparatus: Atlas Ci4000 Xenon		
Weather-Ometer		
Colour fastness to artificial light	651	
DS/EN ISO 105:B02:2014	Colour fastness:	7
Method 2		
1-8 scale, 8 best rating		
Normal conditions		
Apparatus: Atlas Ci4000 Xenon Weather-Ometer		
weather-Officiel		



A 867940-1

Report no.: Appendix: Page: 3 of 3 Initials: Chf/leIn

<b>Test Methods</b>	Results	
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	671 Colour fastness:	6
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	751 Colour fastness:	7
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	761 Colour fastness:	7
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	781 Colour fastness:	6
Colour fastness to artificial light DS/EN ISO 105:B02:2014 Method 2 1-8 scale, 8 best rating Normal conditions Apparatus: Atlas Ci4000 Xenon Weather-Ometer	991 Colour fastness:	7